# Lark Engineering Company (India) Pvt. Ltd.

I.T.I. Sasouli Road, Yamuna Nagar - 135 001 (Haryana)

| Form No. | CNC/QA/FM/02 |
|---|---|
| Rev. No. | 01 |
| Rev. Date | 31-07-2013 |

## Inprocess Inspection (Pellet Dies)

| S.No. | Check Parameter | Specification | Observations | Remarks |
|---|---|---|---|---|
| 1 | Work Order No. | | 9868 | 30/40 |
| 2 | Machined By | | V.T.L. M/c Shop | Dig No. Lark 9109 370 |
| 3 | Pallet Die No. | | 10368 (3.5) MM | |
| 4 | Die Category | Drg. No. | Junior | |
| 5 | Out Side Diameter | Drg. No. | 400 MM Step OD. 395 MM | Step Length. 14.5 |
| 6 | Inside Diameter | Drg. No. | 320.12 MM | |
| 7 | Width of Pellet Die | Drg. No. | 142 MM | |
| 8 | Grooves as per Drawing | Drg. No. | 15.5×7×2 MM / 15.5×7×2 MM | |
| 9 | Fitting Sizes on CNC Plate | Drg. No. | OK | |
| 10 | Drilling Area Surface Smoothness | | OK | |
| 11 | Tapping Operator | | M/C Shop | Tapping No. of holes. 8 Both Side |
| 12 | Tapping PCD | | 355 MM | |
| 13 | Tapping Hole Diameter | | M16 Check by M16 Bolt | |
| 14 | Tapping On Second Side | Half pitch of 1st side | OK | |
| 15 | Tapping Hole Depth | | Drill Depth. 20.5 MM Tapping Depth. 18.8 MM | |
| 16 | Perpendicularity of Tapped Hole | | Yes | |
| 17 | Visual Inspection Before Gun Drilling | | OK | |
| | Inspected By (Sign) & Date | | Ravi 13/7/23 | |
| 1 | As per programme no. | | — | |
| 2 | Gun Drilling Work Completed On | | — | |
| 3 | Hole Finish In Gun Drilling | Marked | OK | |
| 4 | Defective Holes (If Any) | | No | |

**Note :** Mark the defective holes/Missed holes with the help of Permanent Marker

| | | | | | | | | |
|---|---|---|---|---|---|---|---|---|
| 1 | Counter Sinking Depth & Finish | OK | | | | | | Ravi 18 |
| 2 | External Relief Dia | 3.8 MM | Outside (2-2) | | Inner | | | |
| 3 | External Relief Depth | | 14 MM | | 10 MM | | | |
| 4 | Inspection Done Before Hardening By (Name) | | Ravi | | | | | |
| 5 | Material Sent For Hardening By (Name) | | Lark Furnace | | | | | |
| 6 | Material Sent For Hardening On Date | | 13 | 7 | 23 | | | |
| | Inspected By (Sign) & Date | | Ravi 13/7/23 | | | | | |

13/7/23

Reviewed by (Engineer-CNC)

Manager-QA

Scanned with CamScanner