Lark Engineering Company (India) Pvt. Ltd.

I.T.I. Sasouli Road, Yamuna Nagar - 135 001 (Haryana)

Form No.	CNC/QA/FM/02
Rev. No.	01
Rev. Date	31-07-2013

Inprocess Inspection (Pellet Dies)

S.No.	Check Parameter	Specification	Observations	Remarks
1	Work Order No.		12940	28/43/80
2	Machined By		V.T.L. M/c. Shop	Dy No: LS.D-700 Rev:03
3	Pallet Die No.		120 7.2 (6.0) HH	
4	Die Category	Drg. No.	Jumbo	
5	Out Side Diameter	Drg. No.	730 HH, Step OD: 732 HH / 638 HH	
6	Inside Diameter	Drg. No.	572.12 HH	Step length: 30HH / 18.5 HH
7	Width of Pellet Die	Drg. No.	219 HH	Under Cut = 1HH
8	Grooves as per Drawing	Drg. No.	75x8x8 HH / 58x8x8 HH	
9	Fitting Sizes on CNC Plate	Drg. No.	OK	
10	Drilling Area Surface Smoothness		OK	
11	Tapping Operator		M/c. Shop	[Tapping No of Holes: 6
12	Tapping PCD		650 HH	
13	Tapping Hole Diameter		M16 = Check by M16 Bolt	
14	Tapping On Second Side	Half pitch of 1st side	One Side Tapping and IInd Side One Slot	
15	Tapping Hole Depth		Drill Depth: 40.4HH Tapping Depth: 33.5	
16	Perpendicularity of Tapped Hole		yes	
17	Visual Inspection Before Gun Drilling		OK	
	Inspected By (Sign) & Date		Ravi 23/9/24	[1 Slot 32.1 HH Width 19 HH Depth
1	As per programme no.		—	
2	Gun Drilling Work Completed On		—	
3	Hole Finish In Gun Drilling	Marked	OK	
4	Defective Holes (If Any)		No	Slot Rework After Hard.

Note : Mark the defective holes/Missed holes with the help of Permanent Marker

Counter=60 Rows=8

1	Counter Sinking Depth & Finish	OK						
2	External Relief Dia	6.5 HH / 7.0 HH	6.5 HH	All Rows	7.0 HH	All Rows		
3	External Relief Depth			58 HH		37 HH		
4	Inspection Done Before Hardening By (Name)		Ravi					
5	Material Sent For Hardening By (Name)		Lark Furnace					
6	Material Sent For Hardening On Date		23	9	24			
	Inspected By (Sign) & Date		Ravi 23/9/24					

23/9/24.

Reviewed by (Engineer-CNC)

Manager-QA

Scanned with CamScanner