5951

Lark Engineering Company (India) Pvt. Ltd.

I.T.I. Sasouli Road, Yamuna Nagar - 135 001 (Haryana)

Form No.	CNC/QA/FM/02
Rev. No.	01
Rev. Date	31-07-2013

Inprocess Inspection (Pellet Dies)

S.No.	Check Parameter	Specification	Observations	Remarks
1	Work Order No.		10080	38/43
2	Machined By		V.T.L m/c Shop	Drg No. L-S.D. 856
3	Pallet Die No.		10621 (3.0) mm	Rev. 00
4	Die Category	Drg. No.	Extrawide	
5	Out Side Diameter	Drg. No.	606 mm Step OD = 621.5 mm	Tapper = 12°
6	Inside Diameter	Drg. No.	520.12 mm	Step length = 21.5
7	Width of Pellet Die	Drg. No.	222 mm	Undercut = 7.75 mm
8	Grooves as per Drawing	Drg. No.	13x8x5 mm / 13x8x5 mm	
9	Fitting Sizes on CNC Plate	Drg. No.	ok	
10	Drilling Area Surface Smoothness		ok	
11	Tapping Operator		M/C Shop	Tapping No. of Holes 12 Both Side
12	Tapping PCD		565 mm	
13	Tapping Hole Diameter		M20 = Check by M20 Bolt	
14	Tapping On Second Side	Half pitch of 1st side	ok	
15	Tapping Hole Depth		Drill Depth = 20.4 mm Tapping Depth = 18.8	
16	Perpendicularity of Tapped Hole		yes	
17	Visual Inspection Before Gun Drilling		ok	
	Inspected By (Sign) & Date		Ravi 16/8/23	
1	As per programme no.		—	
2	Gun Drilling Work Completed On		—	
3	Hole Finish In Gun Drilling	Marked	ok	
4	Defective Holes (If Any)		No - 1 Hole Colused	

Note : Mark the defective holes/Missed holes with the help of Permanent Marker

1	Counter Sinking Depth & Finish	ok						Row = 38
2	External Relief Dia	3.3 mm	[illegible]	All Lines				
3	External Relief Depth			5 mm				
4	Inspection Done Before Hardening By (Name)		Ravi					
5	Material Sent For Hardening By (Name)		Lark Furnace					
6	Material Sent For Hardening On Date		16	8	23			
	Inspected By (Sign) & Date		Ravi 16/8/23					

Reviewed by (Engineer-CNC)

Manager-QA

Tarawat 16/8/23

Scanned with CamScanner