# Lark Engineering Company (India) Pvt. Ltd.

I.T.I. Sasouli Road, Yamuna Nagar - 135 001 (Haryana)

| Form No. | CNC/QA/FM/02 |
|---|---|
| Rev. No. | 01 |
| Rev. Date | 31-07-2013 |

## Inprocess Inspection (Pellet Dies)

| S.No. | Check Parameter | Specification | Observations | Remarks |
|---|---|---|---|---|
| 1 | Work Order No. | | 13112 | 40/40 2995 |
| 2 | Machined By | | V.T.L H/C Shop | Dy no. Lark 2170 |
| 3 | Pallet Die No. | | 12499 (5.0) HH | |
| 4 | Die Category | Drg. No. | Senior | |
| 5 | Out Side Diameter | Drg. No. | 500 HH, Step OD = 491 HH | Step length 7.5 |
| 6 | Inside Diameter | Drg. No. | 420.12 HH | |
| 7 | Width of Pellet Die | Drg. No. | 158 HH | |
| 8 | Grooves as per Drawing | Drg. No. | 12×8×3 HH / 12×8×3 HH | |
| 9 | Fitting Sizes on CNC Plate | Drg. No. | Ok | |
| 10 | Drilling Area Surface Smoothness | | Ok | |
| 11 | Tapping Operator | | H/C Shop | Tapping No of Holes 8 Both Side |
| 12 | Tapping PCD | | 454 HH | |
| 13 | Tapping Hole Diameter | | M20 = Check by M20 Bolt | |
| 14 | Tapping On Second Side | Half pitch of 1st side | Ok | |
| 15 | Tapping Hole Depth | | Drill Depth. 18.4 HH Tapping Depth. 16-5 | |
| 16 | Perpendicularity of Tapped Hole | | Yes | |
| 17 | Visual Inspection Before Gun Drilling | | Ok | |
| | **Inspected By (Sign) & Date** | | Ravi 23/10/24 | |
| 1 | As per programme no. | | ——— | |
| 2 | Gun Drilling Work Completed On | | ——— | |
| 3 | Hole Finish In Gun Drilling | Marked | Ok | |
| 4 | Defective Holes (If Any) | | No | |

**Note :** Mark the defective holes/Missed holes with the help of Permanent Marker

Counter. 60° Row. 17

| | | | | | | | | |
|---|---|---|---|---|---|---|---|---|
| 1 | Counter Sinking Depth & Finish | Ok | | | | | | |
| 2 | External Relief Dia | 5.3 HH | Outside (2-2) | | Inner | | | |
| 3 | External Relief Depth | | 5 HH | | Mill | | | |
| 4 | Inspection Done Before Hardening By (Name) | | Ravi | | | | | |
| 5 | Material Sent For Hardening By (Name) | | Lark Surface | | | | | |
| 6 | Material Sent For Hardening On Date | | 23 | 10 | 24 | | | |
| | **Inspected By (Sign) & Date** | | Ravi 23/10/24 | | | | | |

Reviewed by (Engineer-CNC) Satish 23/10/24

Manager-QA

Scanned with CamScanner