5965

Lark Engineering Company (India) Pvt. Ltd.

I.T.I. Sasouli Road, Yamuna Nagar - 135 001 (Haryana)

Form No.	CNC/QA/FM/02
Rev. No.	01
Rev. Date	31-07-2013

Inprocess Inspection (Pellet Dies)

S.No.	Check Parameter	Specification	Observations	Remarks
1	Work Order No.		10088	40/50
2	Machined By		V.T.L. M/c Shop	Dy. No. 1-S.D. 976
3	Pallet Die No.		9068 (3.2) HH	Rev. 01
4	Die Category	Drg. No.	SSSTD	
5	Out Side Diameter	Drg. No.	620 HH, Step OD = 614 HH	Tapper = 12°
6	Inside Diameter	Drg. No.	520.12 HH	Step length = 20 HH
7	Width of Pellet Die	Drg. No.	186 HH	Undercut = 8 HH
8	Grooves as per Drawing	Drg. No.	13×8×3 HH / 13×8×3 HH	
9	Fitting Sizes on CNC Plate	Drg. No.	Ok	
10	Drilling Area Surface Smoothness		Ok	
11	Tapping Operator		M/C Shop	Tapping No of Holes 12 Both Side
12	Tapping PCD		565 HH	
13	Tapping Hole Diameter		M20 = Check by M20 Bolt	
14	Tapping On Second Side	Half pitch of 1st side	Ok	
15	Tapping Hole Depth		Drill Depth 20.4 HH Tapping Depth 18.8	
16	Perpendicularity of Tapped Hole		Yes	
17	Visual Inspection Before Gun Drilling		Ok	
	Inspected By (Sign) & Date		Ravi 19/8/23	
1	As per programme no.		———	
2	Gun Drilling Work Completed On		———	
3	Hole Finish In Gun Drilling	Marked	Ok	
4	Defective Holes (If Any)		No	

Note : Mark the defective holes/Missed holes with the help of Permanent Marker

1	Counter Sinking Depth & Finish	Ok						Rev. 29
2	External Relief Dia	3.8 HH	Outside (3-3)		Inner			
3	External Relief Depth		16 HH		10 HH			
4	Inspection Done Before Hardening By (Name)		Ravi					
5	Material Sent For Hardening By (Name)		Lark Furnace					
6	Material Sent For Hardening On Date		19	8	23			
	Inspected By (Sign) & Date		Ravi 19/8/23					

19/8/23

Reviewed by (Engineer-CNC)

Manager-QA

Scanned with CamScanner