8721

Lark Engineering Company (India) Pvt. Ltd.

I.T.I. Sasouli Road, Yamuna Nagar - 135 001 (Haryana)

Form No.	CNC/QA/FM/02
Rev. No.	01
Rev. Date	31-07-2013

Inprocess Inspection (Pellet Dies)

S.No.	Check Parameter	Specification	Observations	Remarks
1	Work Order No.		13157	60/66
2	Machined By		V.T.L. H/C Shop	Dg No. LEC-29136 Rev-01
3	Pallet Die No.		13941(3.5)HH	
4	Die Category	Drg. No.	Single Jumbo	
5	Out Side Diameter	Drg. No.	1032 HH, Step OD 1033 HH	Tapper 3°
6	Inside Diameter	Drg. No.	900.14 HH Ø	Step length 37 HH, 39.2 HH; Under cut 0.5 HH
7	Width of Pellet Die	Drg. No.	37.5 HH	
8	Grooves as per Drawing	Drg. No.	29.5x8x13 HH / 29.5x8x13 HH	
9	Fitting Sizes on CNC Plate	Drg. No.	Ok	
10	Drilling Area Surface Smoothness		Ok	
11	Tapping Operator		H/C Shop	Tapping No of Holes 15 Both Side
12	Tapping PCD		970 HH	
13	Tapping Hole Diameter		M24, Check by M24 Bolt	
14	Tapping On Second Side	Half pitch of 1st side	Ok	
15	Tapping Hole Depth		Drill Depth 38.4 HH	Tapping Depth 36.4 HH
16	Perpendicularity of Tapped Hole		Yes	
17	Visual Inspection Before Gun Drilling		Ok	
	Inspected By (Sign) & Date		Ravi 10/12/24	
1	As per programme no.		—	2 Slot 39.1 HH width 7.5 HH Depth Both Side
2	Gun Drilling Work Completed On		—	
3	Hole Finish In Gun Drilling	Marked	Ok	
4	Defective Holes (If Any)		No	

Note : Mark the defective holes/Missed holes with the help of Permanent Marker

Counter = 60°

1	Counter Sinking Depth & Finish	Ok						Ravi 59
2	External Relief Dia	4.0 HH	Outside (4-4)		Inner			
3	External Relief Depth		13 HH		6 HH			
4	Inspection Done Before Hardening By (Name)		Ravi					
5	Material Sent For Hardening By (Name)		Lark Furnace					
6	Material Sent For Hardening On Date		10	12	24			
	Inspected By (Sign) & Date		Ravi 10/12/24					

Satya 10/12/24.

Reviewed by (Engineer-CNC)

Manager-QA

Scanned with CamScanner