Lark Engineering Company (India) Pvt. Ltd.

I.T.I. Sasouli Road, Yamuna Nagar - 135 001 (Haryana)

Form No.	CNC/QA/FM/02
Rev. No.	01
Rev. Date	31-07-2013

Inprocess Inspection (Pellet Dies)

S.No.	Check Parameter	Specification	Observations	Remarks
1	Work Order No.		13545 /	40/40 /
2	Machined By		V.T.L H/C Shop	Dy No. 1.3 D. 1028 Rev. 00 /
3	Pallet Die No.		13885 (6.0) HH /	
4	Die Category	Drg. No.	Junior	
5	Out Side Diameter	Drg. No.	398 HH / Stock OD = 383 HH	Stock length 10.5
6	Inside Diameter	Drg. No.	$3\frac{18.12}{ID}$ HH / $3\frac{15.12}{ID}$ HH (Bore = 318.12 HH) /	→ Maintained After Hard in Fitting Side
7	Width of Pellet Die	Drg. No.	108 HH /	
8	Grooves as per Drawing	Drg. No.	4 x 5 x 3 HH / 4 x 5 x 3 HH /	
9	Fitting Sizes on CNC Plate	Drg. No.	Ok	
10	Drilling Area Surface Smoothness		Ok	
11	Tapping Operator		H/C Shop	[Tapping No of holes. Both Side
12	Tapping PCD		350 HH /	
13	Tapping Hole Diameter		all 2", Check by 1/2" Tap /	
14	Tapping On Second Side	Half pitch of 1st side	Ok	
15	Tapping Hole Depth		Drill Depth 12.4 HH Tapping Depth. 10.5 HH /	
16	Perpendicularity of Tapped Hole		yes	
17	Visual Inspection Before Gun Drilling		Ok	
	Inspected By (Sign) & Date		Ravi 12/12/24	
1	As per programme no.		—	
2	Gun Drilling Work Completed On		—	
3	Hole Finish In Gun Drilling	Marked	Ok	
4	Defective Holes (If Any)		No	

Note : Mark the defective holes/Missed holes with the help of Permanent Marker

1	Counter Sinking Depth & Finish	Ok						Counter 60° Rev. 11
2	External Relief Dia	6.5 HH /	Outside (2 → 2)		Inner			
3	External Relief Depth		6 HH		Nill			
4	Inspection Done Before Hardening By (Name)		Ravi					
5	Material Sent For Hardening By (Name)		Lark Furnace					
6	Material Sent For Hardening On Date		12	12	24			
	Inspected By (Sign) & Date		Ravi 12/12/24					

Satya 13/12/24.

Reviewed by (Engineer-CNC)

Manager-QA

Scanned with CamScanner