Lark Engineering Company (India) Pvt. Ltd.

I.T.I. Sasouli Road, Yamuna Nagar - 135 001 (Haryana)

Form No.	CNC/QA/FM/02
Rev. No.	01
Rev. Date	31-07-2013

Inprocess Inspection (Pellet Dies)

S.No.	Check Parameter	Specification	Observations	Remarks
1	Work Order No.		13576	40/66/66
2	Machined By		V.T.L H/C Shop	Dgn No. US-0-09 Rev-03
3	Pallet Die No.		13930 (6.0) HH	
4	Die Category	Drg. No.	H. Jumbo	
5	Out Side Diameter	Drg. No.	680.7 HH, Step OD 693 HH	Tapper 8°
6	Inside Diameter	Drg. No.	548.12 HH (Bore 548.0 HH)	Step length 31 HH
7	Width of Pellet Die	Drg. No.	195 HH	Under cut 2.5 HH
8	Grooves as per Drawing	Drg. No.	32 x 7 x 9.2 HH / 32 x 7 x 9.2 HH (4 x 3) HH	
9	Fitting Sizes on CNC Plate	Drg. No.	ok	Face Side Step 2 HH Deep Both Side
10	Drilling Area Surface Smoothness		ok	
11	Tapping Operator		H/C Shop	
12	Tapping PCD		819 HH	Tapping No of Holes 2 Both Side
13	Tapping Hole Diameter		M16 - Check by M16 Bolt	
14	Tapping On Second Side	Half pitch of 1st side	ok	
15	Tapping Hole Depth		Drill Depth. 33.4 HH Tapping Depth - 31.6	
16	Perpendicularity of Tapped Hole		Yes	
17	Visual Inspection Before Gun Drilling		ok	
	Inspected By (Sign) & Date		Ravi 16/12/24	
1	As per programme no.		—	
2	Gun Drilling Work Completed On		—	
3	Hole Finish In Gun Drilling	Marked	ok	
4	Defective Holes (If Any)		No.	

Note : Mark the defective holes/Missed holes with the help of Permanent Marker

1	Counter Sinking Depth & Finish	ok							Counter. 30° Rows 12
2	External Relief Dia	6.5 HH / 7.0 HH	6.5 HH All Rows 2		98 HH				
3	External Relief Depth		7.0 HH All Rows = 6 HH						
4	Inspection Done Before Hardening By (Name)		Ravi						
5	Material Sent For Hardening By (Name)		Lark Furnace						
6	Material Sent For Hardening On Date		16	12	24				
	Inspected By (Sign) & Date		Ravi 16/12/24						

Sanjay 16/12/24.

Reviewed by (Engineer-CNC)

Manager-QA

Scanned with CamScanner