Lark Engineering Company (India) Pvt. Ltd.

I.T.I. Sasouli Road, Yamuna Nagar - 135 001 (Haryana)

Form No.	CNC/QA/FM/02
Rev. No.	01
Rev. Date	31-07-2013

Inprocess Inspection (Pellet Dies)

S.No.	Check Parameter	Specification	Observations	Remarks
1	Work Order No.		13674	33/66
2	Machined By		V.T.L. M/c Shop	40/66
3	Pallet Die No.		13349(8.2) HH	Drg No. LS.D2/095 Rev: 00
4	Die Category	Drg. No.	M. Jumbo	
5	Out Side Diameter	Drg. No.	680 HH, Step OD = 692.5 HH, Tapper = 5°	
6	Inside Diameter	Drg. No.	546.12 HH (Box = 548.12 HH)	Step length = 33 HH
7	Width of Pellet Die	Drg. No.	215 HH	Undercut = 3.15 HH
8	Grooves as per Drawing	Drg. No.	30.5 x 6 x 9.1 HH | 30.5 x 6 x 9.1 HH (6 x 8) HH	
9	Fitting Sizes on CNC Plate	Drg. No.	Ok	Face Side
10	Drilling Area Surface Smoothness		Ok	Step 1 HH
11	Tapping Operator		M/c. Shop	Deep Both Side
12	Tapping PCD		620 HH	Tapping No of Holes = 2
13	Tapping Hole Diameter		M16 = Check by M16 Bolt	
14	Tapping On Second Side	Half pitch of 1st side	Ok	Both Side
15	Tapping Hole Depth		Drill Depth = 32.2 HH Tapping Depth = 30.5 HH	
16	Perpendicularity of Tapped Hole		Yes	
17	Visual Inspection Before Gun Drilling		Ok	
	Inspected By (Sign) & Date		Ravi 2/1/25	
1	As per programme no.		———	
2	Gun Drilling Work Completed On		———	
3	Hole Finish In Gun Drilling	Marked	Ok	
4	Defective Holes (If Any)		No	

Note : Mark the defective holes/Missed holes with the help of Permanent Marker

Counter = 30°

1	Counter Sinking Depth & Finish	Ok						Ravi
2	External Relief Dia	9.0 HH	Ist Pad		IInd Pad			
3	External Relief Depth		33 HH		26 HH			
4	Inspection Done Before Hardening By (Name)		Ravi					
5	Material Sent For Hardening By (Name)		Lark Furnace					
6	Material Sent For Hardening On Date		2	1	25			
	Inspected By (Sign) & Date		Ravi 2/1/25					

Satpal 2/1/25.

Reviewed by (Engineer-CNC)

Manager-QA

Scanned with CamScanner