9087

Lark Engineering Company (India) Pvt. Ltd.

I.T.I. Sasouli Road, Yamuna Nagar - 135 001 (Haryana)

Form No.	CNC/QA/FM/02
Rev. No.	01
Rev. Date	31-07-2013

Inprocess Inspection (Pellet Dies)

S.No.	Check Parameter	Specification	Observations	Remarks
1	Work Order No.		13983 ✓	34/50 ✓
2	Machined By		V.T.L H/C Shop	Dy No. 1.2C.125.01
3	Pallet Die No.		13555(3.0)HN ✓	Rev.01 ✓
4	Die Category	Drg. No.	N. Turbo	
5	Out Side Diameter	Drg. No.	Top HN - Step OD = 698 HN ✓ Tapper = 12°	
6	Inside Diameter	Drg. No.	Bot. 12 HN / Bot. 14 HN Ⓐ	Step length 3 HN
7	Width of Pellet Die	Drg. No.	22 HN ✓	
8	Grooves as per Drawing	Drg. No.	12 x 8 x 7 HN / 12 x 8 x 7 HN ✓	
9	Fitting Sizes on CNC Plate	Drg. No.	ok	
10	Drilling Area Surface Smoothness		ok	
11	Tapping Operator		H/C Shop	Tabbing No of Holes = 12 Both Side
12	Tapping PCD		640 HN ✓	
13	Tapping Hole Diameter		M20 x Check by M20 Bolt ✓	
14	Tapping On Second Side	Half pitch of 1st side	ok	
15	Tapping Hole Depth		Drill Depth. 20.2 HN Tapping Depth 18.6	
16	Perpendicularity of Tapped Hole		yes	
17	Visual Inspection Before Gun Drilling		ok	
	Inspected By (Sign) & Date		Ravi 27/1/25	
1	As per programme no.		—	
2	Gun Drilling Work Completed On		—	
3	Hole Finish In Gun Drilling	Marked	ok	
4	Defective Holes (If Any)		No	

Note : Mark the defective holes/Missed holes with the help of Permanent Marker

Counter = 60° Rev: 39

1	Counter Sinking Depth & Finish	Ok							
2	External Relief Dia	3.5HN ✓	Outside (3-3)		Inner				
3	External Relief Depth		22 HN		16HN ✓				
4	Inspection Done Before Hardening By (Name)		Ravi						
5	Material Sent For Hardening By (Name)		Lark Furnace						
6	Material Sent For Hardening On Date		27	1	25				
	Inspected By (Sign) & Date		Ravi 27/1/25						

Satya 27/1/25.

Reviewed by (Engineer-CNC)

Manager-QA

Scanned with CamScanner