Lark Engineering Company (India) Pvt. Ltd.

I.T.I. Sasouli Road, Yamuna Nagar - 135 001 (Haryana)

Form No.	CNC/QA/FM/02
Rev. No.	01
Rev. Date	31-07-2013

Inprocess Inspection (Pellet Dies)

S.No.	Check Parameter	Specification	Observations	Remarks
1	Work Order No.		10976	39/50 8752
2	Machined By		V.T.L H/C Shop	Dy No: Lark 5570
3	Pallet Die No.		5880 (3.0) HH	
4	Die Category	Drg. No.	5557D	
5	Out Side Diameter	Drg. No.	620 HH Step OD = 612 HH	Step length 19.4
6	Inside Diameter	Drg. No.	520.12 HH	
7	Width of Pellet Die	Drg. No.	~~220 HH~~ 186 HH	
8	Grooves as per Drawing	Drg. No.	13x8x5 HH / 13x8x5 HH	
9	Fitting Sizes on CNC Plate	Drg. No.	Ok	
10	Drilling Area Surface Smoothness		Ok	
11	Tapping Operator		H/C Shop	Tapping No of Holes = 12 Both Side
12	Tapping PCD		565 HH	
13	Tapping Hole Diameter		M20 Check by M20 Bolt	
14	Tapping On Second Side	Half pitch of 1st side	Ok	
15	Tapping Hole Depth		Drill Depth: 20.5 HH Tapping Depth: 18.8	
16	Perpendicularity of Tapped Hole		Yes	
17	Visual Inspection Before Gun Drilling		Ok	
	Inspected By (Sign) & Date		Rao 5/9/23	
1	As per programme no.			
2	Gun Drilling Work Completed On			
3	Hole Finish In Gun Drilling	Marked	Ok	
4	Defective Holes (If Any)		No - 3 Hole Closed (A)	

Note : Mark the defective holes/Missed holes with the help of Permanent Marker

1	Counter Sinking Depth & Finish	Ok							Rao 30
2	External Relief Dia	3.5 HH	Outside (3-31)			Inner			
3	External Relief Depth		21 HH			18 HH			
4	Inspection Done Before Hardening By (Name)		Rao!						
5	Material Sent For Hardening By (Name)		Lark Furnace						
6	Material Sent For Hardening On Date		5	9	23				
	Inspected By (Sign) & Date		Rao 5/9/23						

5/9/23

Reviewed by (Engineer-CNC)

Manager-QA

Scanned with CamScanner