# Lark Engineering Company (India) Pvt. Ltd.

I.T.I. Sasouli Road, Yamuna Nagar - 135 001 (Haryana)

| Form No. | CNC/QA/FM/02 |
|---|---|
| Rev. No. | 01 |
| Rev. Date | 31-07-2013 |

## Inprocess Inspection (Pellet Dies)

| S.No. | Check Parameter | Specification | Observations | Remarks |
|---|---|---|---|---|
| 1 | Work Order No. | | 10209 | 49/58 |
| 2 | Machined By | | V.T.L. N/C Shop | Drg. no. L.T.C.-6986 87 Rev. 00 |
| 3 | Pallet Die No. | | 11011 (3.0) MM | |
| 4 | Die Category | Drg. No. | Jumbo | |
| 5 | Out Side Diameter | Drg. No. | 776 MM, Step OD = 800 MM | Step length = 26 MM |
| 6 | Inside Diameter | Drg. No. | 660.12 MM | Under cut = 12 MM |
| 7 | Width of Pellet Die | Drg. No. | 316 MM | |
| 8 | Grooves as per Drawing | Drg. No. | 20 x 8 x 7.5 MM / 20 x 8 x 7.5 MM | |
| 9 | Fitting Sizes on CNC Plate | Drg. No. | Ok | |
| 10 | Drilling Area Surface Smoothness | | Ok | |
| 11 | Tapping Operator | | N/C Shop | Tapping No. of Holes = 12 Both Side |
| 12 | Tapping PCD | | 725 MM | |
| 13 | Tapping Hole Diameter | | M20 x Check by M20 Bolt | |
| 14 | Tapping On Second Side | Half pitch of 1st side | Ok | |
| 15 | Tapping Hole Depth | | Drill Depth 25.5 MM | Tapping Depth 23.7 |
| 16 | Perpendicularity of Tapped Hole | | Yes | |
| 17 | Visual Inspection Before Gun Drilling | | Ok | |
| | Inspected By (Sign) & Date | | Ravi 7/9/23 | |
| 1 | As per programme no. | | ——— | |
| 2 | Gun Drilling Work Completed On | | ——— | |
| 3 | Hole Finish In Gun Drilling | Marked | Ok | |
| 4 | Defective Holes (If Any) | | No. | |

**Note :** Mark the defective holes/Missed holes with the help of Permanent Marker

| | | | | | | | | |
|---|---|---|---|---|---|---|---|---|
| 1 | Counter Sinking Depth & Finish | Ok | | | | | | Ravi 57 |
| 2 | External Relief Dia | 3.5 MM | Out Side 3.37 | | Inner | | | |
| 3 | External Relief Depth | | 22 MM | | 16 MM | | | |
| 4 | Inspection Done Before Hardening By (Name) | | Ravi | | | | | |
| 5 | Material Sent For Hardening By (Name) | | Lark Furnace | | | | | |
| 6 | Material Sent For Hardening On Date | | 7 | 9 | 23 | | | |
| | Inspected By (Sign) & Date | | Ravi 7/9/23 | | | | | |

7/9/23

Reviewed by (Engineer-CNC)

Manager-QA

Scanned with CamScanner