9353

Lark Engineering Company (India) Pvt. Ltd.

I.T.I. Sasouli Road, Yamuna Nagar - 135 001 (Haryana)

Form No.	CNC/QA/FM/02
Rev. No.	01
Rev. Date	31-07-2013

Inprocess Inspection (Pellet Dies)

S.No.	Check Parameter	Specification	Observations	Remarks
1	Work Order No.		14329	33/50
2	Machined By		V.T.L H/C Shop	Dy No. LEC/998- Rev:00
3	Pallet Die No.		14193(3.0) HH Extra wide	
4	Die Category	Drg. No.		
5	Out Side Diameter	Drg. No.	G19.8 HH @ Step OD Tapper 12°	
6	Inside Diameter	Drg. No.	5 To 12 HH	Step Length 13.5
7	Width of Pellet Die	Drg. No.	222 HH	
8	Grooves as per Drawing	Drg. No.		
9	Fitting Sizes on CNC Plate	Drg. No.	13x8x5 HH | 13x8x5 HH	
10	Drilling Area Surface Smoothness		ok	
11	Tapping Operator		ok	
12	Tapping PCD		H/C Shop	[Tapping No of holes 12 Both Side
13	Tapping Hole Diameter		565 HH	
14	Tapping On Second Side	Half pitch of 1st side	M20 Check by M20 Ro 11	
15	Tapping Hole Depth		ok	
16	Perpendicularity of Tapped Hole		Drill Depth 20.2 HH	Tapping Depth. 8.6
17	Visual Inspection Before Gun Drilling		yes	
	Inspected By (Sign) & Date		ok Ravi 10/3/25	
1	As per programme no.			
2	Gun Drilling Work Completed On			
3	Hole Finish In Gun Drilling	Marked	ok	
4	Defective Holes (If Any)		No	

Note : Mark the defective holes/Missed holes with the help of Permanent Marker

1	Counter Sinking Depth & Finish	ok							Counter 60° Rev: 38
2	External Relief Dia	3.5 HH	Out Side (3-3)		Inner				
3	External Relief Depth		23 HH		17 HH				
4	Inspection Done Before Hardening By (Name)		Ravi						
5	Material Sent For Hardening By (Name)		Lark Furnace						
6	Material Sent For Hardening On Date		10	3	25				
	Inspected By (Sign) & Date		Ravi 10/3/25						

Satya 10/3/25

Reviewed by (Engineer-CNC)

Manager-QA

Scanned with CamScanner