93/5

Lark Engineering Company (India) Pvt. Ltd.

I.T.I. Sasouli Road, Yamuna Nagar - 135 001 (Haryana)

Form No.	CNC/QA/FM/02
Rev. No.	01
Rev. Date	31-07-2013

Inprocess Inspection (Pellet Dies)

S.No.	Check Parameter	Specification	Observations	Remarks
1	Work Order No.		14340	3715
2	Machined By		V.T.L. N/C Shop	Dy No. 12.0298 Rev 00
3	Pallet Die No.		14196 (3.5) HH	
4	Die Category	Drg. No.	Extra wide	
5	Out Side Diameter	Drg. No.	619.8 HH (2) Step OD. Taper 12°	Step length 18.5
6	Inside Diameter	Drg. No.	520.12 HH	
7	Width of Pellet Die	Drg. No.	222 HH	
8	Grooves as per Drawing	Drg. No.	13x8x5 HH / 13x8x5 HH	
9	Fitting Sizes on CNC Plate	Drg. No.	Ok	
10	Drilling Area Surface Smoothness		Ok	
11	Tapping Operator		N/C Shop	Tapping No of holes 12 Both Side
12	Tapping PCD		565 HH	
13	Tapping Hole Diameter		M20 Stack by M20 Bolt	
14	Tapping On Second Side	Half pitch of 1st side	Ok	
15	Tapping Hole Depth		Drill Depth 20.3 HH	Tapping Dept 18.6
16	Perpendicularity of Tapped Hole		Yes	
17	Visual Inspection Before Gun Drilling		Ok	
	Inspected By (Sign) & Date		Ravi 3/3/25	
1	As per programme no.		———	
2	Gun Drilling Work Completed On		———	
3	Hole Finish In Gun Drilling	Marked	Ok	
4	Defective Holes (If Any)		No	

Note : Mark the defective holes/Missed holes with the help of Permanent Marker

Counter 60° Power 35

1	Counter Sinking Depth & Finish	Ok						
2	External Relief Dia	4.0 HH	OutSide (3-3)		Inner			
3	External Relief Depth		20 HH		13 HH			
4	Inspection Done Before Hardening By (Name)		Ravi					
5	Material Sent For Hardening By (Name)		Lark Furnace					
6	Material Sent For Hardening On Date		3	3	25			
	Inspected By (Sign) & Date		Ravi 3/3/25					

Satyam 3/3/25

Reviewed by (Engineer-CNC)

Manager-QA

Scanned with CamScanner