6047

Lark Engineering Company (India) Pvt. Ltd.

I.T.I. Sasouli Road, Yamuna Nagar - 135 001 (Haryana)

Form No.	CNC/QA/FM/02
Rev. No.	01
Rev. Date	31-07-2013

Inprocess Inspection (Pellet Dies)

S.No.	Check Parameter	Specification	Observations	Remarks
1	Work Order No.		10113 to 10163	25/35/66
2	Machined By		V.T.L N/C Shop	Dy. No. L-SD-009
3	Pallet Die No.		10754 (B.O) HH	Rev. 01
4	Die Category	Drg. No.	M. Jumbo	
5	Out Side Diameter	Drg. No.	680.69 HH Step OD: 693 HH	Tapper: 8°
6	Inside Diameter	Drg. No.	548.12 HH	Step length: 91 HH
7	Width of Pellet Die	Drg. No.	195.1 HH	Undercut: 2.5 HH
8	Grooves as per Drawing	Drg. No.	32 x 7 x 8 HH / 32 x 7 x 8 HH (4x8) HH	Face side Step 3 HH
9	Fitting Sizes on CNC Plate	Drg. No.	Ok	Deep Both Side
10	Drilling Area Surface Smoothness		Ok	
11	Tapping Operator		N/C Shop	Tapping No. of Holes: 4 Both Side
12	Tapping PCD		619 HH	
13	Tapping Hole Diameter		M16 : Check by M16 Bolt	
14	Tapping On Second Side	Half pitch of 1st side	Ok	
15	Tapping Hole Depth		Drill Depth: 33.4 HH Tapping Depth: 31.7	
16	Perpendicularity of Tapped Hole		Yes	
17	Visual Inspection Before Gun Drilling		Ok	
	Inspected By (Sign) & Date		Ravi 11/9/23	
1	As per programme no.		—	
2	Gun Drilling Work Completed On		—	
3	Hole Finish In Gun Drilling	Marked	Ok	
4	Defective Holes (If Any)		No	

Note : Mark the defective holes/Missed holes with the help of Permanent Marker

1	Counter Sinking Depth & Finish	Ok							Counter: 30° Rad: 12
2	External Relief Dia	6.5HH / 7.0HH	6.5HH	All Lines		7.0HH	All Lines		
3	External Relief Depth		41HH				31 HH		
4	Inspection Done Before Hardening By (Name)		Ravi						
5	Material Sent For Hardening By (Name)		Lark Furnace						
6	Material Sent For Hardening On Date		11	9	23				
	Inspected By (Sign) & Date		Ravi 11/9/23						

11/9/23

Reviewed by (Engineer-CNC)

Manager-QA

Scanned with CamScanner