Lark Engineering Company (India) Pvt. Ltd.

I.T.I. Sasouli Road, Yamuna Nagar - 135 001 (Haryana)

Form No.	CNC/QA/FM/02
Rev. No.	01
Rev. Date	31-07-2013

Inprocess Inspection (Pellet Dies)

S.No.	Check Parameter	Specification	Observations	Remarks
1	Work Order No.		10490	40/40
2	Machined By		V.T.L. M/c Shop	Dy No. Lark 3195 SS10
3	Pallet Die No.		10696 (5.0) HH	
4	Die Category	Drg. No.	Senior	
5	Out Side Diameter	Drg. No.	500 HH, Step OD = 491 HH	Step length 175
6	Inside Diameter	Drg. No.	420.12 HH	
7	Width of Pellet Die	Drg. No.	158 HH	
8	Grooves as per Drawing	Drg. No.	12×8×3 HH / 12×8×3 HH	
9	Fitting Sizes on CNC Plate	Drg. No.	ok	
10	Drilling Area Surface Smoothness		ok	
11	Tapping Operator		M/c Shop	Tapping No of Holes = 8 Both Side
12	Tapping PCD		454 HH	
13	Tapping Hole Diameter		M20 × Check by M20 Bolt	
14	Tapping On Second Side	Half pitch of 1st side	ok	
15	Tapping Hole Depth		Drill Depth: 19.8 HH Tapping Depth = 174	
16	Perpendicularity of Tapped Hole		yes	
17	Visual Inspection Before Gun Drilling		ok	
	Inspected By (Sign) & Date		Ravi 11/10/23	
1	As per programme no.		———	
2	Gun Drilling Work Completed On		———	
3	Hole Finish In Gun Drilling	Marked	ok	
4	Defective Holes (If Any)		No	

Note : Mark the defective holes/Missed holes with the help of Permanent Marker

1	Counter Sinking Depth & Finish	ok						Row = 17
2	External Relief Dia	5.3 HH	Outside (2-2)		Inner			
3	External Relief Depth		5 HH		Nil			
4	Inspection Done Before Hardening By (Name)		Ravi					
5	Material Sent For Hardening By (Name)		Lark Forge					
6	Material Sent For Hardening On Date		11	10	23			
	Inspected By (Sign) & Date		Ravi 11/10/23					

Sat 11/10/23

Reviewed by (Engineer-CNC)

Manager-QA

Scanned with CamScanner