6239

Lark Engineering Company (India) Pvt. Ltd.

I.T.I. Sasouli Road, Yamuna Nagar - 135 001 (Haryana)

Form No.	CNC/QA/FM/02
Rev. No.	01
Rev. Date	31-07-2013

Inprocess Inspection (Pellet Dies)

S.No.	Check Parameter	Specification	Observations	Remarks
1	Work Order No.		10447	30/38/50 Dy No = L.S.D. 633 Rev = 01
2	Machined By		V.T.L. N/C Shop	
3	Pallet Die No.		10513 (4.0) HH	
4	Die Category	Drg. No.	SSSTD	
5	Out Side Diameter	Drg. No.	690 HH, Step OD = 683.6 HH	Tapper = 12°
6	Inside Diameter	Drg. No.	520.12 HH	Step length = 20 HH
7	Width of Pellet Die	Drg. No.	186 HH	Undercut = 1.8 HH
8	Grooves as per Drawing	Drg. No.	13×8×5 HH / 13×8×5 HH	
9	Fitting Sizes on CNC Plate	Drg. No.	Ok	
10	Drilling Area Surface Smoothness		Ok	
11	Tapping Operator		N/C Shop	Tabbing No of Holes = 12 Both Side
12	Tapping PCD		565 HH	
13	Tapping Hole Diameter		M16 = Check by M16 Bolt	
14	Tapping On Second Side	Half pitch of 1st side	Ok	
15	Tapping Hole Depth		Drill Depth. 20.4 HH Tapping Depth. 18.7	
16	Perpendicularity of Tapped Hole		Yes	
17	Visual Inspection Before Gun Drilling		Ok	
	Inspected By (Sign) & Date		Ravi 11/10/23	
1	As per programme no.		———	
2	Gun Drilling Work Completed On		———	
3	Hole Finish In Gun Drilling	Marked	Ok	Discussed with Mr. Neeraj ji & Sumit ji (Sales)
4	Defective Holes (If Any)		No	

Note : Mark the defective holes/Missed holes with the help of Permanent Marker

1	Counter Sinking Depth & Finish	Ok						Ravi 95
2	External Relief Dia	4.5 HH / 5.0 HH	4.5 HH All Lines		5.0 HH All Lines			
3	External Relief Depth		18 HH		12 HH		→ conditionally accepted.	
4	Inspection Done Before Hardening By (Name)		Ravi					
5	Material Sent For Hardening By (Name)		Lark Furnace					
6	Material Sent For Hardening On Date		11	10	23			
	Inspected By (Sign) & Date		Ravi 11/10/23					

Reviewed by (Engineer-CNC) 11/10/23

Manager-QA

Scanned with CamScanner