6433

Lark Engineering Company (India) Pvt. Ltd. I.T.I. Sasouli Road, Yamuna Nagar - 135 001 (Haryana)	Form No.	CNC/QA/FM/02
	Rev. No.	01
Inprocess Inspection (Pellet Dies)	Rev. Date	31-07-2013

S.No.	Check Parameter	Specification	Observations	Remarks
1	Work Order No.		10644	30/50
2	Machined By		V.T.L. H/C Shop	Dwg No. L.S.C-998 Rev 00
3	Pallet Die No.		110GH (3.0) HH	
4	Die Category	Drg. No.	Extra wide	
5	Out Side Diameter	Drg. No.	620 HH, Step 20. Taper 12° Step length 18.5	
6	Inside Diameter	Drg. No.	520.12 HH	
7	Width of Pellet Die	Drg. No.	22 HH	
8	Grooves as per Drawing	Drg. No.	13x8x5 HH / 13x8x5 HH	
9	Fitting Sizes on CNC Plate	Drg. No.	ok	
10	Drilling Area Surface Smoothness		ok	
11	Tapping Operator		H/C Shop	Tapping No of Holes = 12 Both Side
12	Tapping PCD		565 HH	
13	Tapping Hole Diameter		M20 : Check by M20 Bolt	
14	Tapping On Second Side	Half pitch of 1st side	ok	
15	Tapping Hole Depth		Drill Depth. 20.8 HH Tapping Depth = 19 HH	
16	Perpendicularity of Tapped Hole		Yes	
17	Visual Inspection Before Gun Drilling		ok	
	Inspected By (Sign) & Date		Ravi 16/11/23	
1	As per programme no.			
2	Gun Drilling Work Completed On			
3	Hole Finish In Gun Drilling	Marked	ok	
4	Defective Holes (If Any)		No	

Note : Mark the defective holes/Missed holes with the help of Permanent Marker

1	Counter Sinking Depth & Finish	OK						Ravi 38
2	External Relief Dia	3.5HH	OD Side (3-3)		Inner			
3	External Relief Depth		23HH		20HH			
4	Inspection Done Before Hardening By (Name)		Ravi					
5	Material Sent For Hardening By (Name)		Lark Furnace					
6	Material Sent For Hardening On Date		16	11	23			
	Inspected By (Sign) & Date		Ravi 16/11/23					

Ravi 16/11/23

Reviewed by (Engineer-CNC)

Manager-QA

Scanned with CamScanner