Lark Engineering Company (India) Pvt. Ltd.

I.T.I. Sasouli Road, Yamuna Nagar - 135 001 (Haryana)

Form No.	CNC/QA/FM/02
Rev. No.	01
Rev. Date	31-07-2013

Inprocess Inspection (Pellet Dies)

S.No.	Check Parameter	Specification	Observations	Remarks
1	Work Order No.		10878	414/50
2	Machined By		V.T.L. N/C Shop	Dy No. 1.2 Cr 9980 Rev 00
3	Pallet Die No.		11944 (4.0) HH	
4	Die Category	Drg. No.	Extra wide	
5	Out Side Diameter	Drg. No.	620 HH Step OD = Tapper 12° Step length = 18	
6	Inside Diameter	Drg. No.	520.12 HH	
7	Width of Pellet Die	Drg. No.	222 HH	
8	Grooves as per Drawing	Drg. No.	13×8×5 HH / 13×8×5 HH	
9	Fitting Sizes on CNC Plate	Drg. No.	ok	
10	Drilling Area Surface Smoothness		ok	
11	Tapping Operator		N/C Shop	Tapping No. of Holes = 12 Both Side
12	Tapping PCD		565 HH	
13	Tapping Hole Diameter		M20 = Check by M20 Bolt	
14	Tapping On Second Side	Half pitch of 1st side	ok	
15	Tapping Hole Depth		Drill Depth = 21.4 HH Tapping Depth = 19 HH	
16	Perpendicularity of Tapped Hole		Yes	
17	Visual Inspection Before Gun Drilling		ok	
	Inspected By (Sign) & Date		Ravi 8/12/23	
1	As per programme no.		—	
2	Gun Drilling Work Completed On		—	
3	Hole Finish In Gun Drilling	Marked	ok	
4	Defective Holes (If Any)		No	

Note : Mark the defective holes/Missed holes with the help of Permanent Marker

1	Counter Sinking Depth & Finish	ok						Rev-31
2	External Relief Dia	4.3 HH	Out Side (3.3)		Inner			
3	External Relief Depth		14 HH		6 HH			
4	Inspection Done Before Hardening By (Name)		Ravi					
5	Material Sent For Hardening By (Name)		Lark Furnace					
6	Material Sent For Hardening On Date		8	12	23			
	Inspected By (Sign) & Date		Ravi 8/12/23					

8/12/23

Reviewed by (Engineer-CNC)

Manager-QA

Scanned with CamScanner