Lark Engineering Company (India) Pvt. Ltd.

I.T.I. Sasouli Road, Yamuna Nagar - 135 001 (Haryana)

Form No.	CNC/QA/FM/02
Rev. No.	01
Rev. Date	31-07-2013

Inprocess Inspection (Pellet Dies)

S.No.	Check Parameter	Specification	Observations	Remarks
1	Work Order No.		10857	50/55
2	Machined By		V.T.L H/C Shop	Dy No. 1.E.C2183 81 Rev. 00
3	Pallet Die No.		10885 (6.0) HH	
4	Die Category	Drg. No.	Senior	
5	Out Side Diameter	Drg. No.	530 HH / Step OD 491 HH	Step length 17.5
6	Inside Diameter	Drg. No.	420.12 HH	
7	Width of Pellet Die	Drg. No.	158 HH	
8	Grooves as per Drawing	Drg. No.	12 x 8 x 3 HH / 12 x 8 x 3 HH	
9	Fitting Sizes on CNC Plate	Drg. No.	OK	
10	Drilling Area Surface Smoothness		OK	
11	Tapping Operator		H/C Shop	Tapping No. of Holes = 8 Both Side
12	Tapping PCD		454 HH	
13	Tapping Hole Diameter		M24 Check by M24 Bolt	
14	Tapping On Second Side	Half pitch of 1st side	OK	
15	Tapping Hole Depth		Drill Depth 19 HH Tapping Depth 17 HH	
16	Perpendicularity of Tapped Hole		Yes	
17	Visual Inspection Before Gun Drilling		OK	
	Inspected By (Sign) & Date		Ravi 13/12/23	
1	As per programme no.			
2	Gun Drilling Work Completed On			
3	Hole Finish In Gun Drilling	Marked	OK	
4	Defective Holes (If Any)		No.	

Note : Mark the defective holes/Missed holes with the help of Permanent Marker

1	Counter Sinking Depth & Finish	OK						Ravi 15
2	External Relief Dia	6.5 HH	Outside (2-2)		Inner			
3	External Relief Depth		11 HH		5 HH			
4	Inspection Done Before Hardening By (Name)		Ravi					
5	Material Sent For Hardening By (Name)		Lark Furnace					
6	Material Sent For Hardening On Date		13	12	23			
	Inspected By (Sign) & Date		Ravi 13/12/23					

Sat 13/12/23

Reviewed by (Engineer-CNC)

Manager-QA

Scanned with CamScanner