6628

Lark Engineering Company (India) Pvt. Ltd.

I.T.I. Sasouli Road, Yamuna Nagar - 135 001 (Haryana)

Form No.	CNC/QA/FM/02
Rev. No.	01
Rev. Date	31-07-2013

Inprocess Inspection (Pellet Dies)

S.No.	Check Parameter	Specification	Observations	Remarks
1	Work Order No.		10889	40/50
2	Machined By		V.T.L M/c Shop	Dy No. 1.2.C.16178 Rev 00
3	Pallet Die No.		8884 (4.0) HH	
4	Die Category	Drg. No.	HYEN	
5	Out Side Diameter	Drg. No.	700 HH, Step OD = 702 HH	Step length = 3 HH
6	Inside Diameter	Drg. No.	600.12 HH	Taper = 12°
7	Width of Pellet Die	Drg. No.	265 HH	Undercut = 1 HH
8	Grooves as per Drawing	Drg. No.	15x8x7 HH / 15x8x7 HH	
9	Fitting Sizes on CNC Plate	Drg. No.	ok	
10	Drilling Area Surface Smoothness		ok	
11	Tapping Operator		M/c Shop	Tapping No of holes = 12 Both Side
12	Tapping PCD		640 HH	
13	Tapping Hole Diameter		M20 x Check by M20 Bolt	
14	Tapping On Second Side	Half pitch of 1st side	ok	
15	Tapping Hole Depth		Drill Depth = 21.2 HH Tapping Depth = 19 HH	
16	Perpendicularity of Tapped Hole		Yes	
17	Visual Inspection Before Gun Drilling		ok	
	Inspected By (Sign) & Date		Ravi 18/12/23	
1	As per programme no.		———	
2	Gun Drilling Work Completed On		———	
3	Hole Finish In Gun Drilling	Marked	ok	
4	Defective Holes (If Any)		No	

Note : Mark the defective holes/Missed holes with the help of Permanent Marker

1	Counter Sinking Depth & Finish	ok						Row 39
2	External Relief Dia	4.5 HH	Outside (3-3)		Inner			
3	External Relief Depth		14 HH		10 HH			
4	Inspection Done Before Hardening By (Name)		Ravi					
5	Material Sent For Hardening By (Name)		Lark Furnace					
6	Material Sent For Hardening On Date		18	12	23			
	Inspected By (Sign) & Date		Ravi 18/12/23					

Reviewed by (Engineer-CNC) 18/12/23

Manager-QA

Scanned with CamScanner