6761

Lark Engineering Company (India) Pvt. Ltd.

I.T.I. Sasouli Road, Yamuna Nagar - 135 001 (Haryana)

Form No.	CNC/QA/FM/02
Rev. No.	01
Rev. Date	31-07-2013

Inprocess Inspection (Pellet Dies)

S.No.	Check Parameter	Specification	Observations	Remarks
1	Work Order No.		11034	33/40/50
2	Machined By		V.T.L. N/C Shop	Dy No. 13.2.959 Rev. 02
3	Pallet Die No.		11445 (4.0) HH	
4	Die Category	Drg. No.	Extra wide	
5	Out Side Diameter	Drg. No.	62 HH / Step OD: 622.4 HH	Tapper 12°
6	Inside Diameter	Drg. No.	52.12 HH / 52.14 HH	Step length. 18 HH Undercut. 1.2 HH
7	Width of Pellet Die	Drg. No.	22 HH	
8	Grooves as per Drawing	Drg. No.	13 x 8 x 5 HH / 13 x 8 x 5 HH	
9	Fitting Sizes on CNC Plate	Drg. No.	ok	
10	Drilling Area Surface Smoothness		Ok	
11	Tapping Operator		N/C Shop	Tapping No of Holes. 12 Both Side
12	Tapping PCD		565 HH	
13	Tapping Hole Diameter		H2 : Check by H2 Roll	
14	Tapping On Second Side	Half pitch of 1st side	ok	
15	Tapping Hole Depth		Drill Depth = 21.4 HH Tapping Depth. 18.8 HH	
16	Perpendicularity of Tapped Hole		yes	
17	Visual Inspection Before Gun Drilling		ok	
	Inspected By (Sign) & Date		Ravi 12/1/24	
1	As per programme no.			
2	Gun Drilling Work Completed On			
3	Hole Finish In Gun Drilling	Marked	Ok	
4	Defective Holes (If Any)		No	

Note : Mark the defective holes/Missed holes with the help of Permanent Marker — Counter : 60°

1	Counter Sinking Depth & Finish	Ok							Ravi. 31
2	External Relief Dia	4.3 HH / 4.8 HH	4.3 HH	All Holes		4.8 HH	All Holes		
3	External Relief Depth		18 HH				10 HH		
4	Inspection Done Before Hardening By (Name)		Ravi						
5	Material Sent For Hardening By (Name)		Lark Furnace						
6	Material Sent For Hardening On Date		12	1	24				
	Inspected By (Sign) & Date		Ravi 12/1/24						

Satya 12/1/24

Reviewed by (Engineer-CNC)

Manager-QA

Scanned with CamScanner