Lark Engineering Company (India) Pvt. Ltd.

I.T.I. Sasouli Road, Yamuna Nagar - 135 001 (Haryana)

Form No.	CNC/QA/FM/02
Rev. No.	01
Rev. Date	31-07-2013

Inprocess Inspection (Pellet Dies)

S.No.	Check Parameter	Specification	Observations	Remarks
1	Work Order No.		11200	50/60
2	Machined By		V.T.L H/C Shop	Dy No. 1.2.0 2409 Rev: 00
3	Pallet Die No.		10202 (4.0) HH	
4	Die Category	Drg. No.	@ 53870	
5	Out Side Diameter	Drg. No.	639.8 HH Step OD 610 HH	Step length, 11.4
6	Inside Diameter	Drg. No.	520.12 HH	
7	Width of Pellet Die	Drg. No.	186 HH	
8	Grooves as per Drawing	Drg. No.	13x8x3 HH / 13x8x3 HH	
9	Fitting Sizes on CNC Plate	Drg. No.	OK	
10	Drilling Area Surface Smoothness		OK	
11	Tapping Operator		H/C Shop	Tapping No of Holes = 12 Both side
12	Tapping PCD		565 HH	
13	Tapping Hole Diameter		M20 = Check by M20 Bolt	
14	Tapping On Second Side	Half pitch of 1st side	OK	
15	Tapping Hole Depth		Drill Depth = 31.4 HH	Tapping Depth 13.8
16	Perpendicularity of Tapped Hole		Yes	
17	Visual Inspection Before Gun Drilling		OK	
	Inspected By (Sign) & Date		Ravi 2/2/24	
1	As per programme no.		—	
2	Gun Drilling Work Completed On		—	
3	Hole Finish In Gun Drilling	Marked	OK	
4	Defective Holes (If Any)		No.	

Note : Mark the defective holes/Missed holes with the help of Permanent Marker

Counter = 60°

1	Counter Sinking Depth & Finish	OK						Row = 25
2	External Relief Dia	4.5HH	Outside 3.37		Inner			
3	External Relief Depth		18HH		10HH			
4	Inspection Done Before Hardening By (Name)		Ravi					
5	Material Sent For Hardening By (Name)		Lark Furnace					
6	Material Sent For Hardening On Date		2	2	24			
	Inspected By (Sign) & Date		Ravi 2/2/24					

Reviewed by (Engineer-CNC) 2/2/24

Manager-QA

Scanned with CamScanner