Lark Engineering Company (India) Pvt. Ltd.

I.T.I. Sasouli Road, Yamuna Nagar - 135 001 (Haryana)

Form No.	CNC/QA/FM/02
Rev. No.	01
Rev. Date	31-07-2013

Inprocess Inspection (Pellet Dies)

S.No.	Check Parameter	Specification	Observations	Remarks
1	Work Order No.		11919/.	30/55/75/
2	Machined By		V.T.L H/C Shop	Dgy No. 13.02.824
3	Pallet Die No.		10371 (6.0) HH/	Rev. 00
4	Die Category	Drg. No.	NTED	
5	Out Side Diameter	Drg. No.	782 HH/734 Step OD 777 HH/778 HH/675 HH	
6	Inside Diameter	Drg. No.	572.12 HH/	Step length 42 HH/ 24.5 24.5
7	Width of Pellet Die	Drg. No.	270 HH/	
8	Grooves as per Drawing	Drg. No.	88 x 8 x 12 HH / 106 x 8 x 12 HH	Undercut 27.5
9	Fitting Sizes on CNC Plate	Drg. No.	Ok	
10	Drilling Area Surface Smoothness		Ok	
11	Tapping Operator		N/C Shop	Tapping No of holes 8
12	Tapping PCD		660 HH/	
13	Tapping Hole Diameter		Ø3/4" = C.Lock by Ø3/4" Bolt	
14	Tapping On Second Side	Half pitch of 1st side	One Side Tapping and IInd Side One Slot	
15	Tapping Hole Depth		Drill Depth. 36.5 HH Tapping Depth. 33.7	
16	Perpendicularity of Tapped Hole		Yes	
17	Visual Inspection Before Gun Drilling		Ok	
	Inspected By (Sign) & Date		Ravi 3/2/24	
1	As per programme no.			1 Slot 39 HH width Ø6 HH Depth
2	Gun Drilling Work Completed On			
3	Hole Finish In Gun Drilling	Marked	Ok	
4	Defective Holes (If Any)		No.	

Note : Mark the defective holes/Missed holes with the help of Permanent Marker — Counter 60° Rev. 7

1	Counter Sinking Depth & Finish	Ok						
2	External Relief Dia	6.5 HH / 7.0 HH	6.5 HH	All Rows	7.0 HH	All Rows		
3	External Relief Depth	/ /	45 HH/			30 HH/		
4	Inspection Done Before Hardening By (Name)		Ravi					
5	Material Sent For Hardening By (Name)		Lark Furnace					
6	Material Sent For Hardening On Date		3	2	24			
	Inspected By (Sign) & Date		Ravi 3/2/24					

3/2/24

Reviewed by (Engineer-CNC)

Manager-QA

Scanned with CamScanner