7098

Lark Engineering Company (India) Pvt. Ltd.

I.T.I. Sasouli Road, Yamuna Nagar - 135 001 (Haryana)

Form No.	CNC/QA/FM/02
Rev. No.	01
Rev. Date	31-07-2013

Inprocess Inspection (Pellet Dies)

S.No.	Check Parameter	Specification	Observations	Remarks
1	Work Order No.		11408/	49/47/
2	Machined By		V.T.L H/C Shop	Dy No. L.S.D. 605
3	Pallet Die No.		12079 (3.5) HH/	Root
4	Die Category	Drg. No.	Extra wide.	
5	Out Side Diameter	Drg. No.	614 HH/ Step OD: 614.4 HH	Tapper: 4°
6	Inside Diameter	Drg. No.	520.14 HH/	Step length: 20 HH
7	Width of Pellet Die	Drg. No.	222 HH	Undercut: 0.8 HH
8	Grooves as per Drawing	Drg. No.	13x8x5 HH / 13x8x5 HH/	3 X 3 grove After Hard
9	Fitting Sizes on CNC Plate	Drg. No.	ok	
10	Drilling Area Surface Smoothness		ok	
11	Tapping Operator		H/C Shop	Tapping No of holes: 12 Both Side
12	Tapping PCD		565 HH/	
13	Tapping Hole Diameter		M20 : Check by M20 Bolt/	
14	Tapping On Second Side	Half pitch of 1st side	ok	
15	Tapping Hole Depth		Drill Depth. 20.7 HH Tapping Depth. 18	
16	Perpendicularity of Tapped Hole		yes	
17	Visual Inspection Before Gun Drilling		ok	
	Inspected By (Sign) & Date		Ravi 14/3/24	
1	As per programme no.		———	
2	Gun Drilling Work Completed On		———	
3	Hole Finish In Gun Drilling	Marked	ok	
4	Defective Holes (If Any)		No	

Note : Mark the defective holes/Missed holes with the help of Permanent Marker

1	Counter Sinking Depth & Finish	ok						Counter: 60° Ravi: 35
2	External Relief Dia	41.0 HH/	Outside (3-3)		Inner			
3	External Relief Depth		12 HH/		5 HH/			
4	Inspection Done Before Hardening By (Name)		Ravi					
5	Material Sent For Hardening By (Name)		Lark Furnace					
6	Material Sent For Hardening On Date		14	3	24			
	Inspected By (Sign) & Date		Ravi 14/3/24					

Satya 14/3/24

Reviewed by (Engineer-CNC)

Manager-QA

Scanned with CamScanner