7284

Lark Engineering Company (India) Pvt. Ltd.

I.T.I. Sasouli Road, Yamuna Nagar - 135 001 (Haryana)

Form No.	CNC/QA/FM/02
Rev. No.	01
Rev. Date	31-07-2013

Inprocess Inspection (Pellet Dies)

S.No.	Check Parameter	Specification	Observations	Remarks
1	Work Order No.		11674	45/50
2	Machined By		V.T.L H/C Shop	Drg No. LEC/1376 Rev 00
3	Pallet Die No.		12181 (6.0) HH	
4	Die Category	Drg. No.	Senior	
5	Out Side Diameter	Drg. No.	520 HH, Step OD 491 HH	Step length 17.4
6	Inside Diameter	Drg. No.	420.12 HH	
7	Width of Pellet Die	Drg. No.	158 HH	
8	Grooves as per Drawing	Drg. No.	12 x 8 x 3 HH / 12 x 8 x 3 HH	
9	Fitting Sizes on CNC Plate	Drg. No.	ok	
10	Drilling Area Surface Smoothness		ok	
11	Tapping Operator		H/C Shop	Tapping No of holes 8 Both Side
12	Tapping PCD		454 HH	
13	Tapping Hole Diameter		M20 x Check by M20 Bolt	
14	Tapping On Second Side	Half pitch of 1st side	ok	
15	Tapping Hole Depth		Drill Depth. 18.8 HH Tapping Depth. 15.8	
16	Perpendicularity of Tapped Hole		Yes	
17	Visual Inspection Before Gun Drilling		ok	
	Inspected By (Sign) & Date		Ravi 9/4/24	
1	As per programme no.			
2	Gun Drilling Work Completed On			
3	Hole Finish In Gun Drilling	Marked	ok	
4	Defective Holes (If Any)		No	

Note : Mark the defective holes/Missed holes with the help of Permanent Marker

Counter 60 Ravi 15

1	Counter Sinking Depth & Finish	ok						
2	External Relief Dia	6.5 HH	Outside (2.2)		Inner			
3	External Relief Depth		11 HH		5 HH			
4	Inspection Done Before Hardening By (Name)		Ravi					
5	Material Sent For Hardening By (Name)		Lark Furnace					
6	Material Sent For Hardening On Date		9	4	24			
	Inspected By (Sign) & Date		Ravi 9/4/24					

Satya 9/4/24
Reviewed by (Engineer-CNC)

Manager-QA

Scanned with CamScanner