



LARK ENGG. CO. (INDIA) PVT. LTD

I.T.I SASOULI ROAD, YAMUNA NAGAR, PH. 91-1732-257685,
259685

SERVICE/ VISIT REPORT

Format: LEC/P-38

Project Name : M/s AOV Agro , Uklana, Hissar	Project Location : Uklana, Hissar
Feed Plant: Poultry Feed	Plant 8-10 TPH with 8 Silos.
Plant operation: 8	If Automatic: ☒
Type of Call	General Audit
Name of Service Person (Lark Representative)	Sandeep Kapoor, Dhirendra Kumar & Anil Gupta
Arrival at Site (Date / Time)	4/9/25 at 10: AM
Departure from Site (Date / Time)	4/9/25 at 4: 30 PM
Customer Concern	1. General Audit 2. Maintenance space required for Pellet Bin 3. Frequent Jamming of Poultry Meal through Manual Dumping 4. Inspection Windows mechanism to be upgraded from Bolting to Toggle Clamp.
Action Taken	1. Thorough Inspection of Equipments 2. Dust Collector made operational 3. Bolt fixing of MS Screw Feeder below Bin. 4. Cleaning of Jute Bin cover. 5. Awareness regarding Preventative Maintenance based upon Daily, Weekly, Monthly, Quarterly, Half Yearly & Yearly. 6. Cleanliness Awareness of Equipments. 7. Greasing of Hammer Mill 8. Greasing of Pellet Mill.
Job Completion Status	
Performance after completion of Job	Satisfied ()
General feedback/ comments	Note:- Shortage of Manpower regarding maintenance, cleaning etc. has been observed without which the severe breakdown cannot be avoided.
Client Signature with stamp Representative)	Signature of Service Person (Lark Dhirendra Kumar

Note: During Service, you have to arrange lodging facility (free of cost) to our representative during their stay at your site.

