



# Lark Engineering Company (India) Pvt. Ltd.

I.T.I. Sasouli Road, Yamuna Nagar - 135 001 (Haryana)

Form No.

CNC/QA/FM/02

Rev. No.

01

Rev. Date

31-07-2013

## Inprocess Inspection (Pellet Dies)

S.No.	Check Parameter	Specification	Observations	Remarks
1	Work Order No.		14172 ✓	42/50 ✓ 6355
2	Machined By		V. T. L. H/c Shop	Operator Lark 3310 ✓
3	Pallet Die No.		13839 (3.0) H/c ✓	
4	Die Category	Drg. No.	Ext. outside	
5	Out Side Diameter	Drg. No.	620 H/c, Step 002 612 H/c	Step length 19.5 ✓
6	Inside Diameter	Drg. No.	520.12 H/c ✓	
7	Width of Pellet Die	Drg. No.	222 H/c ✓	
8	Grooves as per Drawing	Drg. No.	13x8x5 H/c   13x8x5 H/c	
9	Fitting Sizes on CNC Plate	Drg. No.	ok	
10	Drilling Area Surface Smoothness		ok	
11	Tapping Operator		H/c Shop	Tapping No. of holes 12 Both Side
12	Tapping PCD		565 H/c	
13	Tapping Hole Diameter		M20 - Check by M20 Bolt	
14	Tapping On Second Side	Half pitch of 1st side	ok	
15	Tapping Hole Depth		Drill Depth 20.3 H/c Tapping Depth 18.0 H/c	
16	Perpendicularity of Tapped Hole		yes	
17	Visual Inspection Before Gun Drilling		ok	

### Inspected By (Sign) & Date

Ins: 17/2/25

1	As per programme no.		_____
2	Gun Drilling Work Completed On		_____
3	Hole Finish In Gun Drilling	Marked	ok
4	Defective Holes (If Any)		No

Note : Mark the defective holes/Missed holes with the help of Permanent Marker

Counter 60°

1	Counter Sinking Depth & Finish	ok							
2	External Relief Dia	3.5 H/c	Outside 23-37		Inner				
3	External Relief Depth		14 H/c		8 H/c				
4	Inspection Done Before Hardening By (Name)				Ins: 17/2/25				
5	Material Sent For Hardening By (Name)				Lark Porrace				
6	Material Sent For Hardening On Date		17	2	25				

### Inspected By (Sign) & Date

Ins: 17/2/25

Reviewed by (Engineer-CNC)

Manager-QA