



I.T.I. Sasouli Road, Yamuna Nagar - 135 001 (Haryana)

CNC/QA/FM/02

01

31-07-2013

Inprocess Inspection (Pellet Dies)

Inspected By (Sign) & Date		OK	27/6/25
1	As per programme no.		
2	Gun Drilling Work Completed On		
3	Hole Finish In Gun Drilling	Marked	OK
4	Defective Holes (If Any)		No

Note : Mark the defective holes/Missed holes with the help of Permanent Marker

1	Counter Sinking Depth & Finish	ok						Counter = 60
2	External Relief Dia	1.0 mm	All Rows					Row = 12
3	External Relief Depth		36 mm					
4	Inspection Done Before Hardening By (Name)		Row:					
5	Material Sent For Hardening By (Name)		Lank Pura race					
6	Material Sent For Hardening On Date		27	6	25			
Inspected By (Sign) & Date			Row: 27/6/25					

Inspected By (Sign) & Date

Ans: 27/6/25

Reviewed by (Engineer-CNC)

Manager-QA