



I.T.I. Sasoull Road, Yamuna Nagar - 135 001 (Haryana)

10264

Form No.

CNC/QA/FM/02

Rev. No.

01

Rev. Date

31-07-2013

Inprocess Inspection (Pellet Dies)

Inspected By (Sign) & Date			
1	As per programme no.		_____
2	Gun Drilling Work Completed On		_____
3	Hole Finish In Gun Drilling	Marked	OK
4	Defective Holes (If Any)		None

Note : Mark the defective holes/Missed holes with the help of Permanent Marker

1	Counter Sinking Depth & Finish	OK						Ravi 159
2	External Relief Dia	4.0mm	28-40		Inner			
3	External Relief Depth		13mm		6mm			
4	Inspection Done Before Hardening By (Name)				Ravi			
5	Material Sent For Hardening By (Name)				Lank Purnace			
6	Material Sent For Hardening On Date		14	7	25			
Inspected By (Sign) & Date			Ravi 14/7/25					

Inspected By (Sign) & Date

Ques: 14/7/25

Reviewed by (Engineer-CNC)

Manager-QA