



I.T.I. Sasouli Road, Yamuna Nagar - 135 001 (Haryana)

CNC/QA/FM/02

01

31-07-2013

Inprocess Inspection (Pellet Dies)

Inspected By (Sign) & Date			OK	
1	As per programme no.		Ravi	5/9/25
2	Gun Drilling Work Completed On		_____	
3	Hole Finish In Gun Drilling	Marked	OK	
4	Defective Holes (If Any)		No	

Note : Mark the defective holes/Missed holes with the help of Permanent Marker

Counter-60°

1	Counter Sinking Depth & Finish	OK						Counter-60
2	External Relief Dia		outside		Internal			Row-22
3	External Relief Depth		6.5 mm	All Rows	15	1		
4	Inspection Done Before Hardening By (Name)		1.0 mm	All Rows	7	1		
5	Material Sent For Hardening By (Name)							
6	Material Sent For Hardening On Date							

Inspected By (Sign) & Date

Ravi 5/9/25

Manager-QA

Reviewed by (Engineer-CNC)